

Impact Ventilator, Model 754, NSN 6530-01-464-0267

The current calibrator/analyzer (Timeter, model RT-200, 6695-01-255-2855) fielded to Army TOE units is not capable of calibrating the model 754, Impact ventilator. To perform calibration on the 754 ventilator, the RT-200 requires a modification that provides an RS232 port and the associated electronics. The unmodified RT-200 can be used to validate calibration. Medical treatment facilities with the 754 ventilator should use the instructions listed here (<http://www.usamma.army.mil/Documents/754.pdf>) to validate calibration. If the ventilators fail any part of this validation procedure or otherwise require services, the ventilators should be sent to the Maintenance Operations Division, Ogden, Utah, for complete service. In the meantime, the USAMMA is working aggressively to identify and procure TMDE that can adequately calibrate the Impact 754 ventilator.